

OPERATING INSTRUCTIONS

WALKAROUND CHECKER

WA-2



Switching on the Checker

Press the yellow power button for two seconds, the lens will light up blue and 'bleep'. The lens will stay blue whilst the power is on.

If the WA does not switch on, it must be charged with the micro-USB cable provided.

Reading a TPMS sensor

Hold the Checker over the TPMS sensor.

The Checker will 'bleep' and the lens will light up based on one of the pressure states identified below.

GREEN: Tyre Pressure OK
AMBER: Maintenance alert
Flashing RED with bleeps: Critical alert

Charging the Checker

Attach the micro-USB cable provided to the Checker and suitable USB supply. Checker will 'bleep' and the lens will flash blue during the charging process. When charging is complete the Checker WA will 'bleep' and the lens will light solid blue until the micro-USB cable is removed.

Low battery indicator:

If the battery of the Checker is low, after taking a pressure reading, the lens will flash blue three times after indicating the pressure reading.

